

AssetRoof Case Study



New Covenant Christian Church

Problem Overview

Addressing budget constraints and roof issues faced by NCCC post-COVID.

01


New Covenant Christian Church faced **significant roof issues** due to budget limitations.

02

The pandemic heightened concerns about **costs**, affecting maintenance and necessary repairs.

03

AssetRoof provided a solution using physical and drone inspections to identify **critical repairs** and cost avoidance.



Innovative Roof Solutions

Leveraging advanced technology to solve budget constraints and roof issues

AssetRoof utilized **drone inspections and thermal imaging** to identify roof issues effectively. This approach enabled targeted repairs, ensuring cost efficiency while addressing the church's needs post-COVID.

Targeted Repairs Achieved

Strategic actions lead to significant cost avoidance for NCCC's roof maintenance

By utilizing drone inspections and thermal imaging, AssetRoof identified **critical repairs**, allowing NCCC to allocate their limited budget **efficiently** and avoid unexpected costs in the future.



“AssetRoof gives us the confidence
that effectively using our funds
while we’re protecting our church
building wisely...”

David Wheeler



AssetRoof Project Highlights




On roof inspection

Leak identification

Drone inspection

Identify changes and monitor



Thermal Imaging

Infrared roof tracking



Contact us today!

(405) 237-5960

chad@assetroof.com

AssetRoof.com